S 355 N1IB JUL 1 1979 V. av No. 10

# 79 MONTANA

Montana State Library
3 0864 1006 1252 5



# ARMY NATIONAL GUARD



MONTANA STATE LIBRARY
930 E Lyndale Ave.
Helena, Montana 59601

## INFORMATION BULLETIN

An official publication. Contains items of both official and unofficial nature. Official items have the full force and effect of orders and Commanders will comply therewith upon receipt.

1 July 1979 VOLUME 21, NUMBER 10 (Effective until 1 July, 1980, unless sooner rescanded or superseded) PART 1. GENERAL PERSONNEL PART 2-VERIFICATION OF 20 YEARS OF QUALIFYING SERVICE FOR RETIREMENT WALVERS FOR PRIOR SERVICE ENLISTMENT OR REENLISTMENTS INTO THE MONTANA NATIONAL GUARD 203 ANNOUNCEMENTS OF MONTANA ARNG TECHNICIAN ASSIGNMENTS 204 TECHNICIAN VACANCIES 205 APPLICATION FOR ENLISTMENT OPERATIONS AND TRAINING PART 3. ADMINISTRATION OF NERVE AGENT ANTIDOTE/TAB SUPPLY PART 4 PART 5. FISCAL AND TRANSPORTATION MAINTENANCE PART 6 NSN 3120-00-437-7207, P/N 11659878, BUSHING, SLEEVE APPLICABLE 601 TO M561/M792 14 TON TRUCK SAFETY PART 7. 701 USE OF DA FORM 285 IN REPORTING ACCIDENTS 702 SAFE TRANSPORTATION OF MATERIAL USING THE M548 CARGO CARRIER CAMOUFLAGE PAITERN PAINTING OF GAS BOTTLES (OXYGEN & ACETYLENE) 703 704 FY 79 1ST QUARTER SURFACE ACCIDENT SUMMARY FACILITIES AND SECURITY PART 8 801 FACILITIES SELF-INSPECTION REPORTS

PART 9.	UNOFFICIAL	
	FEDERAL RECOGNITION	90]
	CHANGE IN PHONE NUMBERS	902
	MT ARNG STRENGTH AS OF 29 JUNE 1979	903

#### PART 2 -- PERSONNEL

- VERIFICATION OF 20 YEARS OF QUALIFYING SERVICE FOR RETIREMENT a. Commanders are urged to double check personnel files to make certain that all personnel with 20 years of qualifying service for settrement have been received or application has been made for a letter of verification.
- b. Under the new Survivors Benefit Plan all claims must be supported by evidence of completion of 20 years creditable service for retirement purposes.
- 202. WAIVERS FOR PRIOR SERVICE ENLISTMENT OR REENLISIMENTS INTO THE MONTANA NATIONAL GUARD. All waivers for prior service enlistments reenlistments for moral and administrative disqualifications insted in NGR 600-200 seed not be resubmitted to TAG if there is evidence that the waiver was or had to be approved by another military headquarters before enlistment. The waivers will be acceptable for enlistment in the Montana Nilional Guard

203 ANNOUNCEMENTS OF MONTANA ARNG TECHNICIAN ASSIGNMENTS The rollowing technician assigning tree by the Internet Archive

POSITION	in 2012 with funding from	GRADE
Geier, Pamela M. Payrol) Clerk	Montana State Library	GS-05
Stiles Doris K. Personnel Clerk	Helen. MT	GS-05
Phillips, Emmett E. Aircraft Mechanic	Helena MI	WG-09
Johnson, Dennis R. Warehouseman	Helena MT	WG-05

204 TECHNICIAN VACANCIES. The following varances are announced in the Montana Army National Guard. Refer to Terhnician Vacancy Annountment posted on unit bulletin boards for details

POSITION Accounts Maint Clerk	LOCATION Halena MT	GRADE GS-05
Admin Supply Tech	Irp N A.r Helena MT	GS-05

http://archive.org/details/informationbulle5075mont

- 205 APPLICATION FOR ENLISTMENT a. DD Form 1966 1-8, Application for Enlistment Do not complete items 17, 18, 19, 20 and 21 on the DD Form 1966/1. REP 63 information in item 37, DD Form 1966 6 may be omitted. Post pages 5-11, 5-12 and 5-14 to show these changed
- b. DD Form 4 1 4.5, Enlistment Resultstment Document Discard all copies of DD Form 4 4 Items 16. 17 and 18 are not used by ARNGUS.

#### PART 3 -- OPERATIONS AND TRAINING

- 301. ADMINISTRATION OF NERVE AGENT ANTIDOTE TAB. a. The doctrine for administration of nerve agent antidote TAB has changed Two TAB Auto-Injector are issued to the individual soldier. In the event of baset of nerve agent symptoms, the new policy requires born injections to be made simultaneously. This replaces the old ductions of waiting fire minites between injections.
- b. This change in doctrine was instituted due to the increased effectiveness of two simultaneous injections. In addition, an individual may be incapacitated due to the effects of either nerve agent or tab before he could administer the second injection.

PART 4 -- SUPPLY

PART 5 -- FISCAL AND TRANSPORTATION

#### DADE A MA METERIANTE

- NSN 3120-00-4-7- 21, P.N. 1 65-878, BUSHING, SLEEVE APPLICABLE TO M561/M792

  1% TON TRUCK a This is to add see that evolute bushings were found to be defentive and should be remited from the lop, by tem. These bushings are gold/yellow in noitr
- b. Those bushings produced under prior confracts that are either white, purple or black in colur, are nor deferrible, and are to be utilized.
- G. Request stanks of NSN  $\pm 120-00-48$  = 20 be insperred and priority basis and the defeative bushings be segregated and scrapped

#### PAPT 7 -- SAFETY

701 USE OF DA FORM 285 IN REPORTING ACCIDENTS a All andidents are reportable through normal command channels to the State Satety Specialist (Mr. Cochran).

- b. DA Form 285 will be prepaired for all accidents, excluding Aircraft mishaps, and will be forwarded through channels to the State Safety Specialist as soon as possible but not later than 19 days after the accident. This requirement applies to accidents involving ARNG Technicians, National Guard (IDT) (AT) (FTTD) (ADT), and State Funded ARNG Employees.
- c. A copy of the completed DA Form 285 must be submitted with line of duty reports, claims for injuries, etc. through the normal channels.
- d. All line of duty, claims, etc. will be returned to sending unit/organization if DA Form 285 is not included.
- 702. SAFE TRANSPORTATION OF MATERIAL USING THE M548 CARGO CARRIER. a. The M548 Cargo Carrier is designed as a cargo and ammunition support carrier. In recent months there has been two serious accidents involving the carrier while transporting fuses and artillery ammunition. Investigation of the accidents indicate that the engine access plates were not in place and a round of ammo or a fuse slipped into the engine compartment and was detonated by friction or heat.
- b. In order to avoid recurrence of this type of accident, users of the M548 Carrier are cautioned to observe the following procedures.
  - 1. Note the Caution Statement Number 3 on the inside of TM 9-2350-247-10, Change 1 dated Jul 77, which states "Don't drive the carrier with any power plant access plate cover or door open or removed unless necessary for maintenance purposes."
  - 2. Cargo carrier access covers are listed in TM 9-2350-247-20P, Fig. 102, Items 21, 25, 27 and 34. Before and after vehicle Serial Number C3506 should be noted. Covers are in stock.
  - 3. The Bulkhead Protector, NSN 2510-00-041-4907, P/N 11647635, furnished with the material handling kit should be installed, especially when carrying artillery ammunition and fuses.
  - 4. Page 2-64 of TM 9-2350-247-10 provides general precautions for loading cargo and ammunition. Page 2-66 also provides loading charts. These charts and precautions must be followed.
- c. The two accidents resulted in the loss of one life, serious injury of one troop, lesser injuries of two troops and total destruction of two carriers. If the procedures as cited in Para b above as well as the  $-10~\mathrm{TM}$  are followed, accidents of this type will not reoccur.
- d. A caution to have access covers in place and the use of the bulkhead protector when hauling ammo will be added in the next change to TM 2350-247-10.

### 703. CAMOUFLAGE PATTERN PAINTING OF GAS BOTTLES (OXYCEN & ACETYLENE.)

REFERENCE- P S. Magazine dated April 1979, SUBJ: Camouflage Gas Bottles.

- a. Referenced article on Camouflage Painting of Gas Bottles will not be complied with until further notice.
- b. The Department of Army Proponent of AR 750-58, the Army Camouflage Paint Program is currently working on camouflage policy as it pertains to safety items. Until further guidance is received from D. A. curtail camouflage painting of gas bottles.
- 704. FY 79 1ST QUARTER SURFACE ACCIDENT SUMMARY. The ARNG experienced 309 motor vehicle accidents and 445 non-vehicular accidents (I.E., Training, Maintenance & Repair, etc.) during the 1st quarter, FY 79. These accidents resulted in 420 disabling injuries and four (4) fatalities. Motor vehicle property damage recorded during this period was \$250.186.00; non-vehicular accident costs amounted to \$451,943.00

#### PART 8 -- FACILITIES AND SECURITY

801. Reminder that the semi-annual "Facilities Self-Inspection Reports" for the period ending 30 June, are now due in the Adjutant General's Office.

#### PART 9 -- UNOFFICIAL

901. FEDERAL RECOGNITION. The following officers received Federal Recognition:

WINNINGHOFF, WILLIAM T. CW2 100B 516-48-2962	Air Trp 163d AC	8	Nov	78
COLLENBORNE, KENNETH C. MAJ Armor 516-42-3463	HHT 163d AC	8	Mar	79
ETZWILLER, DAVID J. CPT Armor 517-48-5342	HHD Mont ARNG	8	Max	79

902. CPT Ken Cottrill has moved from the Facilities Office to the Administration Office His new phone number is 449-2709. CW4 Richard Williams has changed phones, his new number is 449-2736.

### 903. MT ARNG STRENGTH AS OF 29 JUNE 1979.

		AUT	HORIZED			2	ASSIGNED	
UNIT	OFF	MO	EM/EW	AGGR	OFF	WO	EM/EW	AGGR
St Hq & Hq Det	43	9	39	91	49	9	71	129
HHT(-) 163d AC	28	3	118	149	26	2	86	114
Air Trp (-) 163d AC	15	23	114	152	12	23	75	110
Det 1 Air Trp 163d AC	1	8	48	57	2	8	41	51
3669th Maint Co	6	8	156	170	4	7	117	128
103d PA Det	4	0	9	13	4	0	12	16
Det 1 HHT(-) 163d AC	4	24	56	84	11	16	55	82
1049th Engr (FFTG)	1	0	23	24	1	0	22	23
HHT(-) 1/163d AC	14	4	119	137	13	4	88	105
Det 1 HHT 1/163d AC	2	0	50	52	1	0	30	31
Trp A(-) 1/163d AC	3	0	74	77	3	0	47	50
Det 1 Trp A 1/163d AC	2	0	71	73	7	0	39	40
Trp B(-) 1/163d AC	2	0	43	45	1	0	22	23
Det 1 Trp B 1/163d AC	1	0	54	55	1	0	45	46
Det 2 Trp B 1/163d AC	2	0	48	50	2	0	29	31
Trp C(-) 1/163d AC	3	0	74	77	4	0	72	76
Det 1 Trp C 1/163d AC	2	0	71	73	2	0	30	32
Co D(-) 1/163d AC	3	0	47	50	2	0	30	32
Det 1 Co D 1/163d AC	2	0	40	42	2	0	30	32
How Btry(-) 1/163d AC	6	0	52	58	4	0	41	45
Det 1 HB 1/163d AC	2	0	67	69	2	0	34	36
HHT (-) 2/163d AC	14	4	119	137	10	3	91	104
Det 1 HHT 2/163d AC	2	0	50	52	2	0	38	40
Trp E(-) 2/163d AC	3	0	74	77	2	0	50	52
Det 1 Trp E 2/163d AC	2	0	71	73	2	0	38	40
Trp F(-) 2/163d AC	3	0	74	77	4	0	60	64
Det 1 Trp F 2/163d AC	2	0	71	73	2	0	57	59
Trp G(-) 2/163d AC	3	0	74	77	5	0	57	62
Det 1 Trp G 2/163d AC	2.	0	71	73	2	0	52	54
Co H 2/163d AC	3	0	47	50	3	0	34	37
How Btry 2/163d AC	8	0	119	127	6	0	70	76
Det 1 Co H 2,163d AC	2	0	40	42	2	0	28	30
Co C(-) 5th SF Bn	9	0	57	66	8	0	44	52
Det 1 Co C 5th SF Bn	5	0	25	30	5	0	17	22
Command & Control Hq		0	55	62	6	0	26	32
TOTAL	211	83	2320	2614	206	72	1678	1956
	CHANC	GE FRO	M LAST I	MONTH	-1	NC	NC	1

